






CSA-RAD cannot operate
with RHF310 opamp.
Needs $\pm 5V$ AD8005.

For AD8005 $\pm 5V$ operation
replace LDOs with wire bridge



\$Id: PreampsTest.sch 63 2010-03-19 08:56:40Z stephan \$

TITLE \$Date: 2010-03-19 09:56:40 +0100 (Fr, 19 Mär 2010) \$

FILE: PreampsTest.sch

REVISION: \$Revision: 63 \$

PAGE OF

DRAWN BY: \$Author: stephan \$