

SO-CAU-OHB-RP-50**1. INSPECTED UNIT**

Part number	---
Part name:	STEP-Analog
Serial number	AD1

2. INSPECTION TYPE

Type of inspection (solder, coating, final ...)	solder / gluing
	Pass/ Fail/ Comments
Connectors/Saver	Pass / NA
Hardware assembly	C
Gluing	Pass
Soldering	Pass
Cleanliness	Pass

3. RESULTS

Part acceptable?	PCB accepted / zur weiteren Verarbeitung freigegeben

4. COMMENTS



Build due to Manufacturing Flow Chart: **STEP-Analog-Board-OHB-XI-11**
See WE SO-CAU-OHB-RP-47


5 SIGNATURE

Inspection performed: M. Quack
Name


29.03.2016
Date


Signature





CAU Analog FM



CAU Analog FM

