


*Abb 3 Crack at Capacitor C309*




*Abb 4 Crack at Capacitor C309 detail*






*Abb 5 Crack on Pin 1 & at IC301*




*Abb 6 Crack on Pin 1 &2 at IC301 detail 01*





*Abb 7 Crack on Pin 1 & 2 at IC301 detail 02*



*Abb 8 Crack at Capacitor C302*