

		WE Inspektion Report		Date: 22.03.2016	
SO-CAU-OHB-RP-46					
1. INSPECTED UNIT					
Projekt		CAU Solar Orbiter			
Part name / number:		STEP LVPS Board			
Model		FM			
Serial number		AA 1			
2. INSPECTION TYPE					
Type of inspection (solder, coating, final ...)		Wareneingang			
		Pass/ Fail/ Comments			
Connectors/Saver		P			
Hardware assembly		P			
Gluing		P			
Soldering		P			
Cleanliness		C			
3. RESULTS					
Part acceptable?		Verpackung in Ordnung, keine Beschädigungen			
4. COMMENTS					
Build to Manufacturing Flow Chart: STEP-LVPS-Board-OHB-11-XI Bei zwei Lötstellen von X301 noch Flussmittelreste.					
5 SIGNATURE					
Inspection performed: <u>S. Vital</u>		<u>22.03.2016</u>			
Name		Date		Signature	